



Service Information



[2010 Chevrolet Camaro](#)

[Camaro VIN F Service Manual](#)

Document ID: 2570108

#PIC5320A: Adding Radio Steering Wheel Control Switch (RPO NZL) - (Jan 26, 2011)



Adding Radio Steering Wheel Control Switch (RPO NZL)

Subject:

Models: 2010-2011 Chevrolet Camaro

This PI was superseded to update model years. Please discard PIC5320.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern:

A customer may inquire if it is possible to install steering wheel mounted audio controls on a vehicle that was not originally built with that option.

Recommendation/Instructions:

It is possible to install audio Steering Wheel Controls (SWC) at the customer's expense. This modification will require installation of the appropriate right hand steering wheel control switch, steering wheel pad accessory harness, and recalibration of the BCM. You may need to contact Techline Customer Support Center (TCSC) for a VCI number to recalibrate the BCM. Since this is not a warrantable repair, TCSC may charge a fee for this service.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT
VOLUNTARY
TECHNICIAN
CERTIFICATION

© 2011 General Motors. All rights reserved.