

Date: 11/24/2014 Ref. number: Service / Service Operations / G_0000205212

Subject: 2014/2015 Z51 and Z06 Corvettes – Additional Required Maintenance

To: Chevrolet, Buick, GMC, and Cadillac Dealers

2014/2015 Z51 and Z06 Corvettes - Additional Required Maintenance

The following message only applies to dry sump Corvettes that have not had their first oil change performed.

Some 2014/2015 Z51 and Z06 Corvettes may experience a condition that leads to oil leaking out from the air cleaner assembly. This condition may be caused by running the engine continuously at a high engine speed with the first factory fill oil, resulting in silicone sealants in the engine's gaskets degrading the oil's anti-foaming agents. The oil foam has no effect on the engine's durability.

Effective Immediately:

GM is changing the required maintenance schedule for all 2014/2015 Z51 and Z06 Corvettes equipped with dry sump systems. The new schedule will require the oil/filter be changed immediately after the break-in period, which occurs after the first 500 miles of operation. Once the break-in oil change is performed and the Oil Life Monitoring system is reset, customers should follow the Oil Life Monitoring system for all future oil change needs.

New Maintenance Schedule:

Maintenance Schedule Addi- tional Required Services - Normal	12 000 km/7,500 mi	24 000 km/1 5,000 mi	36 000 km/22,500 mi	48 000 km/30,000 mi	60 000 km/37,500 mi	72 000 km/45,000 mi	84 000 km/52,500 mi	96 0 00 km/5 0,000 mi	108 000 km/67,500 mi	120 000 km/75,000 mi	132 000 km/82,500 mi	144 000 km/90,000 mi	156 000 km/97,500 mi	168 000 km/105,000 mi	180 000 km/112,500 mi	192 000 km/120,000 mi	204 000 km/127,500 mi	216 000 km/135,000 mi	228 000 km/142,500 mi	240 000 km/150,000 mi
Dry Sump Engines Only (Z51 a the first 800 km/500 mi. Follow															ngii	ne o	il an	d filt	er a	fter
Perform Required Services. Check engine oil level and oil life percentage. Change engine oil and filter, if needed.	~	✓	✓	~	√	✓	√	~	√	✓	V	V	V	√	V	~	√	√	✓	✓
Replace passenger compart- ment air filter. (1)			~			~			V			V			V			1		
Inspect evaporative control system. (2)		Tr.				1						V		45				✓		

The 2nd printing of the 2015 Owner Manuals is being updated with this change. These manuals will not be in the glove box material until January 2015. For vehicles produced before this change, and for all vehicles going forward, it is important to notify the customers that a change has been made, and they will need to have the vehicle's oil changed after the break-in period. Copies of the new maintenance grid will be available on GMPROGRAMINFO.com, under Chevrolet, Resources.

As you are aware, all 2014/2015 Corvettes come with Chevrolet Complete Care which covers 2 years/24,000 miles of select required maintenance. Previously, up to 4 service events were allowed under the program guidelines in the 2-year/24,000-mile period. With the change in the maintenance schedule being effective immediately, an additional oil change allowance will be added to 2014/2015 Z51 and Z06 Corvettes, increasing the amount of coverage to 2 years/24,000 miles, up to 5 service events.

Please make sure all dealership personnel are aware of this change.

Message Attachment(s):

2015 Corvette Owner's Manual Update.pdf Acrobat PDF (56.31KB)

11-24-14 Copy of this message G 0000205212 - 2014-2015 Z51 and Z06 Corvettes - Additional Required Maintenance.pdf Acrobat PDF (66.60KB)

Contact name: Jeff Strausser

E-Mail: jeff.strausser@gm.com

Department: Customer Care & Aftersales WHQ

Phone:

Intended roles: Business/Accounting Manager, Customer Relations Manager, Dealer, Dealer Principal, Fleet Sales Consultant, Fleet/Commercial Manager, General Manager, General Manager, General Manager, Internet Sales Manager, Internet Sales Manager, Internet Sales Manager, New Sales Consultant, New Vehicle Sales Manager, Parts & Service Director, Parts Manager, Sales Functions, Sales Management, Service Advisor, Service Manager, Service Technician, Warranty Administrator

Archives: 12/24/2014 Expires: 11/24/2020